

# Guyard Welding Glove 1567 350 DM pH



#### **SPECIFICATIONS**

- · Welder's glove in bovine crust.
- · Intermediate risks Cat. II.

#### **CHARACTERISTICS**

- · Gloves in bovine crust.
- · Red color.
- · Fully lined with fleece.
- · Sewn with 100% aromatic polyamide thread.
- · Palm and thumb crust reinforcement, brown color.
- · Available sizes: 9 to 10.

# CONFORMANCE

- · Declaration issued by Leitat (Spain)  $n^{\circ}0162$  EN 420/03 +A1/09 407/04 EN 388/16 ISO 13997 EN 12477/2001 TYPE A.
- · EU declaration 2016/425 available on guyard-sa.fr.

#### **RECEIVED USES**

· MIG, MAG & ARC welding gloves.



#### PERFORMANCE NEIGHBOURS

· Abrasion : 4/4 Cutting EN 388 / 2016: 1/5 4/4 · Tear: · Perforation : 4/4 Cutting EN ISO 13997: B/F Behavior to fire : 4/4 Contact heat: 1/4 Convective heat : 3/4 · Radiant heat : 3/4 · Small splashes of liquid metal : 4/4 · Large liquid metal splashes : Χ

#### PRECAUTIONS OF THE LAW

- · Wear gloves on dry and clean hands. Pre-testing of gloves is recommended as actual use conditions may differ from EU type testing.
- · Before reuse, check the gloves for defects, holes, tears or abnormal wear.

## **PROTECTION LIMITES**

- Do not use for handling objects with a temperature above 100°C.
- · Do not use for handling chemicals or liquids.

### SAFETY, COMFORT & DEXTERITY

- Dexterity, level 1.
- · These gloves do not contain substances at levels known or suspected to have adverse effects on the hygiene or health of the user under the foreseeable conditions of use.

#### CONDITIONNEMENT

· Bag : 12 pairs. · Boxes: 60 pairs.

# MAINTENANCE AND STORAGE

- · No particular maintenance is recommended. It is recommended to store the products in a cool, dry and ventilated place, away from light.
- · The destruction at the end of life must be controlled and respect the European requirements of traceability and respect of the environment.

Belgium Web: www.contipharma-protect.com